


W3150A+/W5100 Errata Sheet

Document History

Ver 1.0.0 (OCT. 27, 2007)	First release (erratum 1)
Ver 2.0.0 (SEP. 10, 2008)	Add W5100 solution for erratum 1
	Remove Recommendation for erratum 1
Ver 2.1 (APR. 5, 2010)	Remove the erratum solution for W5100 in
	v2.0 and bring back the recommendation of
	v1.0
Ver 2.2 (FEB. 17, 2012)	Add erratum 2, 3
Ver 2.3 (MAR. 5, 2012)	Add a solution for erratum 2, 3

 $\ensuremath{\mathbb{C}}$ Copyright 2012 WIZnet Co., Ltd. All rights reserved.








Solution	In case of W3150A+,
	If you can monitor the RXDV signal (in MII interface), you can solve this problem.
	Before you execute SEND/SENDMAC command in UDP/IP-Raw mode, check
	the value of RXDV signal is '0'. That means there is no received data packet, so you can avoid the errata condition.
	Refer to following pseudo-code.
	/* Change sendto() function */
	Function sendto()
	{
	While $(RXDV == '1')$;
	SEND command;
	/* Complete Sending */
	}
Recommendat ion	In case of W5100,
	We don't have solution but we can give a recommendation.
	After complete a transmission process, check whether Sn_TX_RD and
	Sn_TX_WR have same values or not. If both values are still different, close
	the socket and reset by force.
	/* Change sendto() function */
	Function sendto()
	{
	/* Complete Sending */
	/* wait until Sn_TX_WR and Sn_TX_RD are same */
	While (Sn_TX_WR != Sn_TX_RD)
	{
	wait some time;
	loop_cnt++; if (loop_cnt > CONST_BLOCK_CNT) goto RESET
	i (loop_cht > CONST_BLOCK_CNT) goto RESET





© Copyright 2012 WIZnet Co., Ltd. All rights reserved.

4/7

W3150A+/W5100 Errata Sheet



Example pseudo code:

/* Global variable declaration for subnet mask value */

unsigned char subnet_val[4];

/* W5100 initialization function */

Function Initialize_W5100()

/* Clear the subnet mask register */

IINCHIP_WRITE(SUBR0, 0);

IINCHIP_WRITE(SUBR1, 0);

IINCHIP_WRITE(SUBR2, 0);

IINCHIP_WRITE(SUBR3, 0);

/* Save the right subnet mask value if the subnet is 255.255.255.0 */

subnet_val[0] = 255;

subnet_val[1] = 255;

subnet_val[2] = 255;

 $subnet_val[3] = 0;$

/* TCP connect function */ *Function TCP_Connect(*)

/* Set the subnet mask register to the right value using the variable */
IINCHIP_WRITE(SUBR0, subnet_val[0]);
IINCHIP_WRITE(SUBR1, subnet_val[1]);

IINCHIP_WRITE(SUBR2, subnet_val[2]);

IINCHIP_WRITE(SUBR3, subnet_val[3]);

* Execute TCP connect command */ IINCHIP_WRITE(Sn_CR(socket), Sn_CR_CONNECT);

/* Wait for command done */

while(Sn_CR(socket));

/* Clear the subnet mask register again and keep it */

IINCHIP_WRITE(SUBR0, 0);

IINCHIP_WRITE(SUBR1, 0);





W3150A+/W5100 Errata Sheet



Erratum 3	
Phenomenon	Assuming that the IP address of W5100 is "0.0.0.0" and the gateway, subnet mask is valid (not "0.0.0.0"), the W5100 set the target IP address of ARP request to the gateway IP address not the target node IP address when sends ARP request to another node. So the peer node cannot receive the ARP request from the W5100.
Condition	Normal Node+'ARP Request with+'W5100/W7100A+'IP: 192.168.1.3+'Wrong Target IP address: 192.168.1.254+'IP: 0.0.0+'SN: 255.255.255.0+'Morm ally m ust be 192.168.1.3+'SN: 255.255.255.0+'GW: 192.168.1.254+'Morm ally m ust be 192.168.1.3+'GW: 192.168.1.254+'The W5100 miss calculates the sub-network location when sends the ARPrequest if its own IP address is "0.0.0.0". In the same condition, even if thegateway IP address is "0.0.0.0", the W5100 sends ARP request to "0.0.0.0" IPaddress because the W5100 sends ARP request to the gateway.
Solution	The reason of this erratum3 is same as erratum2 so the solution is also same with erratum2. Please refer to the solution of erratum2.